

Each units TX and RX functionality is tested and judged with a pass/fail criteria during production. Units meeting the criteria continue through production and others are returned for diagnostics.

Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Dynastream Innovations, Inc.  
Models: ANTAP2M4IB and ANTAP2M5IB  
Test #: 090702A SN:404  
Test to: CFR47 Parts 2 and 15.249, RSS-210  
File: 06r1695 TunPr

FCC ID#: O6R1695  
IC: 3797A-1695  
Page 1 of 1  
Date: August 20, 2009