

## **Tune Up Procedure**

### **1. OBAPA1011**

- AFTER PRESSING THE PTT AND CHECK THE TX POWER AT THE CH. 1,  
ADJUST R505 OR C501 TO MEET 0.34W