





The components for supervision the voltage of the buffer battery (IC17, R58, R59, R60) are not equipped!

HFE 3000.4	
Otto Bilz GmbH & Co Vogelsangstr. 8 D-73760 Ostfildern Germany	
Edition	Changed by
Date	Date
	Date: 12/04/1998
	Name: H. Esslinger
	ID No.:
	page 4 of 4



HFE 3000.4

XX = TEST-PAD NO. XX

Edition		Changed by	Date

Otto Bilz GmbH & Co	
Ugelsangstr. 8 D-73760 Ostfildern	
Germany	
Date:	12/04/1998
Name:	H. Esslinger
ID No.:	
Page	1 of 4

One channel RF-receiver for an unmodulated carrier signal (72 MHz - 73 MHz)