

FCC ID: OIWBD AESMR50W90
731 Confirmation: TC725243
Ref Number: 11012

Comment 1:
Grant has been corrected.

Comment 2:
The system did not allow us to do this at the time. This has been discussed with George Tannahill to correct. Grant has been corrected

Comment 3:
The following was provided by the applicant:
Regarding compliance with section 90.219, these requirements mostly relate to a licensee and cannot be defined by manufacturer. For example:
90.219(a)- comply refer to operational description;
90.219(b)- ERP should be a license issue as the manufacturer does not provide any specific antenna;
90.219(c)- comply refer to test report: DEKRAD_FCC.15558_rev2, paragraph 4.2;
90.219(d)- license issue, refer also to repeater overview in operational description;
90.219(e)- license issue;
90.219(f)- license issue.
Please, let me know if you need something else.

Comment 4:
Grant has been corrected