



Intertek Testing Services

ETL SEMKO

Report No.: 9901280

Mode: Charging

Tested By: Hong, Report No.: 9901280

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: X QF

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9901280

Made: Charging

Tested By: Hong, Report No.: 9901280

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
0.46000	21.2	48.0

* limit exceeded

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9901280

Made: Standby

Tested By: Hong, Report No.: 9901280

Scan Settings (1 Range):

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: X QP

Transducer No.	Start	Stop	Name
3	9k	30M	EI076

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB



PAGE 1

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9901280

Mode: Standby

Tested By: Hong, Report No.: 9901280

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9901280

Mode: Transmission

Tested By: Hong, Report No.: 9901280

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10K	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: X QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



PAGE 1

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9901280

Mode: Transmission

Tested By: Hong, Report No.: 9901280

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
0.45000	21.9	48.0

* limit exceeded

Ctrl. No.: N/A