






**Figure 373: Spurious Emissions at Antenna Terminal 256QAM, 1932.5MHz,
B.W. 5MHz, Sub Carrier 30 kHz**



**Figure 374: Spurious Emissions at Antenna Terminal 256QAM, 1962.5MHz,
B.W. 5MHz, Sub Carrier 30 kHz**



**Figure 375: Spurious Emissions at Antenna Terminal 256QAM, 1992.5MHz,
B.W. 5MHz, Sub Carrier 30 kHz**




Figure 376: Spurious Emissions at Antenna Terminal 256QAM, 1935.0MHz,
B.W. 10MHz, Sub Carrier 15 kHz




Figure 377: Spurious Emissions at Antenna Terminal 256QAM, 1962.5MHz,
B.W. 10MHz, Sub Carrier 15 kHz




Figure 378: Spurious Emissions at Antenna Terminal 256QAM, 1990.0MHz,
B.W. 10MHz, Sub Carrier 15 kHz




Figure 379: Spurious Emissions at Antenna Terminal 256QAM, 1935.0MHz,
B.W. 10MHz, Sub Carrier 30 kHz




Figure 380: Spurious Emissions at Antenna Terminal 256QAM, 1962.5MHz,
B.W. 10MHz, Sub Carrier 30 kHz




Figure 381: Spurious Emissions at Antenna Terminal 256QAM, 1990.0MHz,
B.W. 10MHz, Sub Carrier 30 kHz




Figure 382: Spurious Emissions at Antenna Terminal 256QAM, 1935.0MHz,
B.W. 10MHz, Sub Carrier 60 kHz




Figure 383: Spurious Emissions at Antenna Terminal 256QAM, 1962.5MHz,
B.W. 10MHz, Sub Carrier 60 kHz




Figure 384: Spurious Emissions at Antenna Terminal 256QAM, 1990.0MHz,
B.W. 10MHz, Sub Carrier 60 kHz