



BELL[®] Phones
BY NORTHWESTERN BELL PHONES

USOC Connector: RJ11C

Model: 36267 REN: XXX
Telephone Equipment HAC
Made in China
Complies with Part 68 FCC Rules
FCC ID: OK836267
FCC Reg. No.: XXXXXXXX
Distributed Exclusively by Unical
Enterprises, Inc.
Shenzhen Baoan Hantong Electronics Factory



BELL[®] Phones
BY NORTHWESTERN BELL PHONES


USOC Connector: RJ11C

Model: 36267 REN: XXX
Telephone Equipment HAC
Made in China
Complies with Part 68 FCC Rules
FCC ID: OK836267
FCC Reg. No.: XXXXXXXX
Distributed Exclusively by Unical
Enterprises, Inc.
Shenzhen Baoan Hantong Electronics Factory

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause Undesired operation. Privacy of communications may not be ensured when using this phone.



Serial No: BD-104100001-A



Model: 36267
FCC ID: OK836267

BELL[®] Phones
BY NORTHWESTERN BELL PHONES

2.4 GHz

NEED HELP?

Call (800) 888-8990
M-F between 8 AM-
4:30 PM PST

▲ IMPORTANT INFORMATION

Prior to initial use or when you hear a beep sound while the BATT LOW indicator blinks, recharge the handset by placing it in its cradle in the base unit overnight.

If handset loses dial tone, place handset in base for 5 seconds. This will reset security code and restore dial tone.

IN USE PAGE CHARGE

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause Undesired operation. Privacy of communications may not be ensured when using this phone.

