

Sensar, Inc.
FCC ID: OKSNS2PAR

Notes

1. Schematic for the ViCam Parallel Camera Board (Sensar Part Number: 101321ALT-1) is not available since it is a purchased item from the vendor. This board has RF source (Highest RF Source) operating at 20 MHz.
2. Agent Authorization Letter and Anti-Drug Abuse Certificate received from the Sensar are on the file at the Unisys and available at the request.

Dipak Patel
Technical Staff Engineer, Unisys