



(3) EUT Photo




(4) EUT Photo




(5) EUT Photo



(6) EUT Photo



(7) EUT Photo




FCC Report No.: 00BH026FI  
Accredited Lab. of NVLAP(NIST)  
NVLAP Lab. Code : 200347-0




**QuieTek Corporation**  
EMC Test Laboratory

Page: 6 of 21  
Rev.1


(8) EUT Photo




(9) EUT Photo




(10) EUT Photo




(11) EUT Photo




(14) EUT Photo




(15) EUT Photo




(16) EUT Photo



(17) EUT Photo



(18) EUT Photo




FCC Report No.: 00BH026FI  
Accredited Lab. of NVLAP(NIST)  
NVLAP Lab. Code : 200347-0



**QuieTek Corporation**  
EMC Test Laboratory

Page: 15 of 21  
Rev.1

(19) EUT Photo




FCC Report No.: 00BH026FI  
Accredited Lab. of NVLAP(NIST)  
NVLAP Lab. Code : 200347-0




**QuieTek Corporation**  
EMC Test Laboratory

Page: 16 of 21  
Rev.1

(20) EUT Photo



(21) EUT Photo



(22) EUT Photo

