

TEST REPORT: 73-6773 FCC ID: OPQ2MOD-6413

Page 84 of 123






Inside view of 2MOD-6413-xxxx

TEST REPORT: 73-6773 FCC ID: OPQ2MOD-6413


Page 85 of 123



Component side of the board (with RF cans installed)


TEST REPORT: 73-6773 FCC ID: OPQ2MOD-6413

Page 86 of 123



Component side of the board (with RF cans removed)

TEST REPORT: 73-6773 FCC ID: OPQ2MOD-6413 Page 87 of 123



Solder side of board