

# A

Federal Communications Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia, MD 21046

Dear FCC:

When form 731 was filled out electronically, a mistake was made in the product code part of the FCC ID number for the Scitronics CS1000 System consisting of the DSP1000 Receiver (WI10-02) and the BT10-02 Transmitter. The correct FCC ID Number should be OPTDSP1000QT900. Please correct accordingly.

Thank you,

Kristi Iwen  
EMC Technical Secretary  
Intertek Testing Services  
7435 4<sup>th</sup> Street North  
Oakdale, MN 55128