

Request for Class II Permissive Change

FCC ID: OU9AW8001-LS

Data: December 02, 2014

TO: Federal Communication Commission

Please be notified that we, the undersigned, Guangdong Transtek Medical Electronics Co., Ltd declare that the reasons for this Class II permissive change are as below:

1. Update Host.

Please refer to below form for detailed information:

| Item | Key Components Deviation | | Remark |
|------|---|----------------------------|--|
| | LS203-B GBF-1251-B, GBF-1251-B1, GBF-1251-B1 Plus, BF-1255-B, BF-1255-B1, BF-1255-B1 Plus | | |
| Host | Wireless control Body Fat Analyzer | Glass Body Fat Analyzer | Model difference being the appearance, model name, shell and software. |

Thank you.

Sincerely,

ZHONGSHAN TRANSTEK MEDICAL ELECTRONICS CO., LTD
中大正心医疗电子有限公司
2014.12.02
Zhongshan Transtek Electronics Co., Ltd
Tel: +86-760-88282982-230
Fax: +86-760-85339231
Email: kevintan@transtek.cn