

Chris Harvey

From: Christy Le [cle@kyocera-wireless.com]
Sent: Friday, May 12, 2006 5:21 PM
To: Chris Harvey
Cc: cli@kyocera-wireless.com
Subject: RE: Kyocera Wireless Corp. , FCC ID: OVFKWC-K24B, Assessment NO.: AN06T5757, Notice#1

Attachments: Exhibit 8_OVFKWC-K24B_ Internal Photos.pdf



Exhibit
VFKWC-K24B_ Inter
Chris,

Attached is a revised Internal Photo. Please review and let me know if you have any questions.

Thanks,
Christy

At 02:38 PM 5/12/2006 -0400, Chris Harvey wrote:

>Christy, you must respond to the Internal Photo issue from #3 below, as
>this is a long standing policy from the FCC for devices that are
>provided to the General Public.

>

>Best regards,

>

>Chris Harvey

>

>-----Original Message-----

>From: Christy Le [mailto:cle@kyocera-wireless.com]
>Sent: Friday, May 12, 2006 2:30 PM
>To: charvey-tcb@ccsemc.com
>Cc: Christy Le
>Subject: Re: Kyocera Wireless Corp. , FCC ID: OVFKWC-K24B, Assessment NO.:
>AN06T5757, Notice#1

>

>Hi Chris,

>

>Attached is the response for Notice#1 part 1.

>For Internal Photos, please let me know what action should I take?

>However, I am applying for a separate application for BT portion and
>will be done by 1pm.

>Thanks,

>Christy

>

>At 03:54 AM 5/12/2006 -0700, charvey-tcb@ccsemc.com wrote:

>>Christy,

>>

>>I have reviewed the above referenced TCB application and find that
>>the following items need to be addressed before the review can be completed:

>>

>>1. The FCC has released CDMA2000 SAR Measurement guidance. Please
>>show evidence of compliance with determining the worst case RC/SO
>>combination keeping in mind that the FCC recommendation is S055
>>loopback for Rev 6 systems or higher.

>>

>>2. Please provide Schematic Diagrams for this handset (only Bluetooth
>>Schematics were provided)

>>

> >3. The Internal Photos have several component markings that have been
> >blacked-out. Please either confirm that all production samples will
> >also be blacked-out or provide photos where the numbers are legible.
> >
> >4. This device contains a Bluetooth transmitter. It appears as though
> >a separate application to cover this Bluetooth portion of this FCC ID
> >may have been filed under AN06T5756, but the exhibits provided so far
> >are not for the Bluetooth portion. Since the Bluetooth portion has a
> >different Equipment Class (DSS) from the rest of the handset (PCE)
> >the separate application must be filed. Please confirm if AN06T5756
> >has been submitted to cover the Bluetooth portion of this application.
> >
> >The items indicated above must be submitted before processing can
> >continue on the above referenced application. Failure to provide the
> >requested information within 30 days of the original e-mail date may
> >result in application dismissal and forfeiture of the filing fee.
> >Also, please note that partial responses increase processing time and
> >should not be submitted. Any questions about the content of this
> >correspondence should be directed to the e-mail address listed below the name of the
sender.
> >
> >Best regards,
> >Chris Harvey
> >charvey-tcb@ccsemc.com