



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

May 21, 2004

RE: FCC ID: OWDTR-0033-E_ATCB001357

Attention: Denis Lalonde

I have a few comments on this Application.

1. Please note that the transient frequency response plots do not appear to be as expected. Please confirm that the transient frequency response plots are correct and not analyzer trace error.



Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.