

Appendix N: Internal Photographs



Photograph 11: Front without Cover




Photograph 12: Top Cover Removed



Photograph 13: Top Cover and Shield Removed




Photograph 14: Bottom Cover Removed




Photograph 15: Bottom Cover and Shield Removed




Photograph 16: Bottom Cover and Shield Removed2




Photograph 17: Audio Logic Board Component Side Complete View




Photograph 18: Audio Logic Board Component Side Left




Photograph 19: Audio Logic Board Component Side Right




Photograph 20: Audio Logic Board Solder Side Complete View




Photograph 21: Audio Logic Board Solder Side Left Side




Photograph 22: Audio Logic Board Solder Side Right Side




Photograph 23: TRX Syn Board Component Side Complete View




Photograph 24: TRX Syn Board Component Side Upper Left




Photograph 25: TRX Syn Board Component Side Upper Right




Photograph 26: TRX Syn Board Component Side Lower Left




Photograph 27: TRX Syn Board Component Side Lower Right




Photograph 28: TRX Syn Board Solder Side Complete View




Photograph 29: TRX Syn Board Solder Side Upper Left



Photograph 30: TRX Syn Board Solder Side Upper Right



Photograph 31: TRX Syn Board Solder Side Lower Left



Photograph 32: TRX Syn Board Solder Side Lower Right