



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

April 12, 2007

RE: Targus Gropu International, Inc.

FCC ID: OXM000007

After a review of the submitted information, I have a few comments on the above referenced Application. Depending on your responses, kindly understand there may be additional comments.

- 1) Please update the block diagram to show appropriate oscillators of the device as can be found in the schematic.
- 2) FYI...Please note the incorrect limits appear to be applied to 9150 MHz.

Timothy R. Johnson  
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.