

TIMCO ENGINEERING INC.
849 NW State Road 45
Newberry, Florida 32669

Date : December 18, 2008

Subject : Reply for your question. Job 2906KC8
FCC ID: OZ5URCMX6000I (WiFi Portion)

Dear TEI,

Thanks for your question.

I would like to answer to your question for the Job 2906KC8 (OZ5URCMX6000I) as below;

Question > SAR REPORT: There is no EUT Conducted Output Power measurement shown on the SAR TEST REPORT. There must be correlation between the EMC Test Report and the SAR Test Report Output Power. The maximum output power shown on the EMC Report is 17.98 dBm. The SAR Test Report must show the measured output power and it must be within ?0.5 dBm. Please confirm the measurement for the SAR Report. We cannot submit it without this measurement. Thank you.

Answer> Please find the revised SAR test Report in accordance with your guidance. Thank you.


File Name: URCMX6000I_TstRpt(SAR)_Rev1.pdf

The revised report was uploaded at your web site.

Please find it and, if you have any questions or comments on it, please do not hesitate to contact me.

I look forward to hearing your favorable reply soon.

Best Regards,



Tae-Sig(Ted) Park, Technical Manager
Gumi College EMC Center