

Report No.: 0318062(S1)
Model No.: 78401

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement

MKR 17.625 msec

tip

REF 97.0 dB μ V

AT 10 dB


.14 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By:

LR
(Loren Wong)

Date:

15/11/03

Checked By:

[Signature]
(Anthony Chen)

Date:

9/12/03

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

Report No.: 0318062(S1)
Model No.: 78401

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement

MKA 1.5000 msec

REF 97.0 dB μ V

AT 10 dB


.09 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: Kendall Wong

Date: 15/11/03

Checked By: Anthony Chan

Date: 9/12/03

Test Result : Pass / Fail NA

CENTER 27.145 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 30.0 msec

INTERTEK TESTING SERVICES

Report No.: 0318062(S1)

Model No.: 78401

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement


MKA 450.00 μ sec

REF 97.0 dB μ V

AT 10 dB

.00 dB

PEAK
LOG
10
dB/



VA SB
SC FC
CORR

Tested By:

(Kornel Wong)

Date:

15/11/03

Checked By:

(Anthony Chan)

Date:

9/12/03

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

Report No.: 0318062(S1)
Model No.: 78401

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement

hp

MKR 17.625 msec

REF 97.0 dBμV

AT 10 dB


-.01 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: [Signature]
(Feng Wong)

Date: 15/11/03

Checked By: [Signature]
(Phong Chon)

Date: 9/12/03

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 75.0 msec