

US Tech Test Report:
FCC ID:
IC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Class II Permissive Change
P2SMRXV4
4171B-MRXV4
21-0028
March 16, 2021
Neptune Technology Group
MRX920v4

INTERNAL PHOTOGRAPHS



Figure 1. Overall Internal View

US Tech Test Report:
FCC ID:
IC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Class II Permissive Change
P2SMRXV4
4171B-MRXV4
21-0028
March 16, 2021
Neptune Technology Group
MRX920v4



Figure 2. AIP Board

US Tech Test Report:
FCC ID:
IC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Class II Permissive Change
P2SMRXV4
4171B-MRXV4
21-0028
March 16, 2021
Neptune Technology Group
MRX920v4



Figure 3. AIP Board Removed (Top View)

US Tech Test Report:
FCC ID:
IC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Class II Permissive Change
P2SMRXV4
4171B-MRXV4
21-0028
March 16, 2021
Neptune Technology Group
MRX920v4




Figure 4. AIP Board Removed (Bottom View)

US Tech Test Report:
FCC ID:
IC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Class II Permissive Change
P2SMRXV4
4171B-MRXV4
21-0028
March 16, 2021
Neptune Technology Group
MRX920v4




Figure 5. AIP Board, RF Circuit (Shield Removed)