


INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)





INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)




INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)




INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)




INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)




INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)




INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)



INTERTEK TESTING SERVICE

Report No.: HK12071029-2

Equipment Photographs

Model: KL4883

(Internal)

