



Intertek Testing Services

ETL SEMKO

Report No.: 0202218 |
Mode: Talk

Tested By: Hong, Report No.: 0202218 |

Scan Settings (1 Range)

Frequency			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Att'n	Preamp	OpRng
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0598



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 02022181
Mode: Talk

Tested By: Hong, Report No.: 02022181

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement

no Results