

Appendix C – SAR Test Setup Photos



Test Position Back 0 mm Gap

Note: All cables are removed prior to testing.



Test Position Left 0 mm Gap

Note: All cables are removed prior to testing.



Test Position Right 0 mm Gap

Note: All cables are removed prior to testing.



Test Position Laptop 0 mm Gap

Note: All cables are removed prior to testing.



Front of Device Tablet Mode



Back of Device Tablet Mode



Front of Device Laptop Mode