



NOKIA CORPORATION
Joensuunkatu 7
Salo, FIN-24101
Finland
Tel. +358-71-8008000
Fax +358-71-8044235

(7/2/2007)

Federal Communications Commission
Authorization & Evaluation Division,
7435 Oakland Mills Road,
Columbia, MD. 21046

Attention: Equipment Authorization Branch

Correspondence Reference number: 32521,(PDNRM-159)

Question 1: Filing is somewhat unclear about antenna type and location please clarify.

Answer 1: The Bluetooth and WLAN transceivers share an loop type of antenna, which is located at the side of the phone(which is described in revised internal photographs document.). The antenna is fixed and the device has no connection to external antenna.

Revised internal photograph document uploaded to FCC server.

Revised BT & WLAN theory of operation document uploaded to FCC server.

NOKIA CORPORATION
Tero Huhtala