



9F, No. 584, Ray-Guang Road, Taipei, Taiwan, R.O.C.
Tel: +886-2-2659-6669 Fax: +886-2-2659-6577 Email: bob@colortac.com Http://www.colortac.com

Dear Leon:

The following descriptions are our solutions

1: Fig (9) and Fig (24)

We attached two copper types (top & bottom) for getting better connection

Between LCD PANEL and Main Board Chassis.

So we will do this process in our factory,

I think it's no problem

2: Fig (10),(11),(16),(18),(19),(20)

We attached lots of copper types (boundary) for getting better connection

Between Metal Cover and Main Board Chassis.

We will improve mechanical structure and add two screws to get the same effect

If necessary, we will attach copper types like sample.

3: Fig (12) --- OSD Function Control Board (Front Side)

I think this picture has no problem

Best Regards

James_Jao 2001/01/05