















Appendix G. Schematics

FCC ID : PFMTC7730
Report No:E03.0718.FCC.404N
Issue of Date : July 18, 2003



Appendix G. Schematics

FCC ID : PFMTC7730
Report No:E03.0718.FCC.404N
Issue of Date : July 18, 2003



Appendix G. Schematics

FCC ID : PFMTC7730
Report No:E03.0718.FCC.404N
Issue of Date : July 18, 2003



Appendix G. Schematics

FCC ID : PFMTC7730
Report No:E03.0718.FCC.404N
Issue of Date : July 18, 2003



Appendix G. Schematics

FCC ID : PFMTC7730
Report No:E03.0718.FCC.404N
Issue of Date : July 18, 2003



Appendix G. Schematics

FCC ID : PFMTC7730
Report No:E03.0718.FCC.404N
Issue of Date : July 18, 2003



Appendix G. Schematics

FCC ID : PFMTC7730
Report No:E03.0718.FCC.404N
Issue of Date : July 18, 2003




Appendix G. Schematics

FCC ID : PFMTC7730
Report No:E03.0718.FCC.404N
Issue of Date : July 18, 2003



Appendix G. Schematics

FCC ID : PFMTC7730
Report No:E03.0718.FCC.404N
Issue of Date : July 18, 2003





Appendix G. Schematics

FCC ID : PFMTC7730
Report No:E03.0718.FCC.404N
Issue of Date : July 18, 2003



Appendix G. Schematics

FCC ID : PFMTC7730
Report No:E03.0718.FCC.404N
Issue of Date : July 18, 2003

