



HERMON LABORATORIES

February 14, 2005

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. Timothy Johnson, Examining Engineer

RE: your e-mail dated February 9, 2005; Airspan Networks Ltd.
FCC ID: PIDAIRSPAN-58, ATCB002094

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) The corrected file "Description_Txpower_16117_rev1" was uploaded on February 14, 2005 via Operational Description folder.
- 2) The corrected file "User_Guide_partial_16117_section2" was uploaded on February 14, 2005 via User Guide folder (please refer to page 2-3, second Warning).
- 3) The EUT was tested under the maximum available output power (minimum cable loss) supplied to the antenna.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories