



FCC ID:PIDMMAX25

Company name: Airspan Networks Inc.
Address: 777 Yamato Rd, Suite 310
Boca Raton, Florida 33431
USA

MicroMAX 2.5 GHz Tune up procedure

Each MicroMAX radio has been tested by automatic test station. As part of the test, the maximum RF output power value has been measured. In case the RF output power is higher than specified in the System Description, the MicroMAX radio doesn't pass the test and get Fail status.

The MicroMAX boards with Fail status cannot be assembled as part of the final product.

Name of authorized person: Zion Levy
Position: Compliances & Testing Engineer

A handwritten signature in black ink, appearing to read "ZL".

Date: June 17, 2009