



FCC ID:PIDMMAX49

Company name: Airspan Networks (Israel) Ltd
Address: 1 Harava St, "Unitronics" building
Airport City 70100, P.O.199
Israel

MicroMAX 4.9GHz tune up procedure

Each MicroMAX radio has been tested by automatic test station. As part of the test , the Maximum RF output power value has been measured. In case the RF output power is higher than specified in the System Description, the MicroMAX radio does not pass the test and gets Fail status.

MicroMAX boards with Fail status cannot be assembled as part of the final product.

Name of authorized person: Zion Levy
Position: Compliances & Testing Engineer

A handwritten signature in black ink, appearing to read "ZL".

Date: March 25, 2008

Airspan Networks (Israel) Ltd., Israel
Tel: +972-3-9777444 ; Fax: +972-3-9777400, www.airspan.com