

Response 2 to E05-000045-1

1. A new confidentiality letter has been uploaded.
2. A new confidentiality letter has been uploaded.
3. Antenna installation instructions have been uploaded.
9. DC voltages
10. The revised confidentiality letter requests that the tune-up procedure be kept confidential.
13. Per 90.210(k)(3), the spectral emissions mask is correct because this is a non-multilateration transmitter.
14. Documentation of antennas information has been uploaded.