

Helen Zhao

Subject: FW: NEWQ SYSTEM CO., LTD., FCC ID: POHVNQ201, Assessment NO.: AN05T4744, Notice#1



POHVNQ201_Repo
rt(Rev.).doc

From: schong
Sent: Wednesday, April 27, 2005 6:48 PM
To: Helen Zhao
Subject: Re: NEWQ SYSTEM CO., LTD., FCC ID: POHVNQ201, Assessment NO.: AN05T4744, Notice#1

Dear Ms. Helen,

Thank you for your quick process.
The corrected "OSC. OR CRY. FREQ.(FREQ.>=1MHz)" is 14.318MHz, so please refer to attached revised test report.
If you have any question, please feel free to contact us.
Thank you and have a great day!

Best Regards,

S. C. Hong / Project Engineer

> From: Compliance Certification Services [mailto:hzhao@ccsemc.com]
> Sent: Wednesday, April 27, 2005 3:35 PM
> To: Helen Zhao
> Subject: NEWQ SYSTEM CO., LTD., FCC ID: POHVNQ201, Assessment NO.:
> AN05T4744, Notice#1
>
>
> Question #1: The test report lists 24.576 MHz and 16 MHz on the Main Board as "OSC. OR CRY. FREQ.(FREQ.>=1MHz)", which does not agree with the information on the Block Diagram. Please explain.
>
> Best Regards,
> Helen Zhao
>
> The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.