



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

April 11, 2004

RE: Procure International Co.

FCC ID: POSEF-6208

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The FCC ID label appears to be placed on the battery cover. Note that this is not considered a permanent part of the EUT as defined in 2.925(d)(1). Please correct and submit new labeling for this device.
- 2) The 731 form appears to state 881 MHz instead of 88.1 MHz. Please correct.
- 3) It can not be determined from the test report if the device was rotated about all 3 axis to determine worse case positioning. Since the device is expected to be used in a variety of applications/positions, this should have been tested in all 3 axis. Where scans or prescans performed to evaluate all 3 axis Please confirm this was done or evaluate as necessary.
- 4) The 4th harmonic results are higher than the fundamental. This is in violation of Section 15.209(c) & 15.215(b) of the Commission's Rules.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.