



BANDAI(H.K.)CO.,LTD.
Room 2902, 29/F, United Centre,
95 Queensway, Hong Kong.
TEL:(852)2866 0229 FAX:(852)2527 1971

APPENDIX C

To: Federal Communications Commission

Dear Sir/Madam,

As present grantee of the product with FCC ID: PQ391441, we hereby confirm that any of our production units (transmitters) bearing the model #91441 & model #91442 are identical in cosmetics, materials, electrical, mechanical, and physical design, including **Software/firmware and they are different in packaging and changing a small head shape on receiver only.**

The FCC ID for the model #91442 is PQ391442.

Dated this 04 day of April 20 06

A handwritten signature in black ink, appearing to read "Thomas Wong KO".

By

Signature

Printed :Thomas Wong KO

Title QA Manager



BANDAI(H.K.)CO.,LTD.
Room 2902, 29/F, United Centre,
95 Queensway, Hong Kong.
TEL:(852)2866 0229 FAX:(852)2527 1971

Reason for Change of FCC ID:

We have a new model #91442 and would like to change the FCC ID for the previous
granted model #91441.

A transmitter of Model #91441 (previous granted) & #91442 (new model) are
identical in cosmetics, material, electrical, mechanical, and physical design,
including software/firmware and they are different in packaging and changing
a small head shape on receiver.

Notes: Please provide the reason for the change of FCC ID other than grant the permission to a new
responsible party.