



BANDAI(H.K.)CO.,LTD.
Room 2902, 29/F, United Centre,
95 Queensway, Hong Kong.
TEL:(852)2866 0229 FAX:(852)2527 1971

To: Federal Communications Commission

Dear Sir/Madam,

As present grantee of the product with FCC ID: PQ391443, we hereby confirm that any of our production units transmitters bearing the model #91443 and #94060 are identical in cosmetics, materials, electrical, mechanical, and physical design, including software/firmware and they are different in packaging and changing the body shape on receiver only. The FCC ID for the model#94060 is PQ394060.

Dated this 25 day of August, 2006

A handwritten signature in black ink, appearing to read "Thomas Wong Kwok On".

By _____
Signature

Thomas Wong Kwok On
Printed

Title QA Manager



BANDAI(H.K.)CO.,LTD.
Room 2902, 29/F, United Centre,
95 Queensway, Hong Kong.
TEL:(852)2866 0229 FAX:(852)2527 1971

Reason for Change of FCC ID:

We have a new model #94060 and would like to change the FCC ID for the previous granted model #91443. A transmitter of Model #91443 (previous granted) & #94060 (new model) are identical in material, electrical and mechanical including software/firmware and they are different in packaging and changing the body shape on receiver.