



5MHz_High_16QAM_1@24




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:46:53

5MHz_High_16QAM_25@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:47:30

10MHz_Low_QPSK_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:49:38

10MHz_Low_QPSK_50@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:50:05

10MHz_Low_16QAM_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:50:34

10MHz_Low_16QAM_50@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:51:01

10MHz_High_QPSK_1@49




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:51:30

10MHz_High_QPSK_50@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:52:20

10MHz_High_16QAM_1@49




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:53:09

10MHz_High_16QAM_50@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:53:57

15MHz_Low_QPSK_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:55:59

15MHz_Low_QPSK_75@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:56:28

15MHz_Low_16QAM_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:56:57

15MHz_Low_16QAM_75@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:57:25

15MHz_High_QPSK_1@74




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:57:55

15MHz_High_QPSK_75@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:58:53

15MHz_High_16QAM_1@74




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 23:59:54

15MHz_High_16QAM_75@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 3.APR.2025 00:00:54

20MHz_Low_QPSK_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 3.APR.2025 00:02:55

20MHz_Low_QPSK_100@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 3.APR.2025 00:03:26

20MHz_Low_16QAM_1@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 3.APR.2025 00:03:57

20MHz_Low_16QAM_100@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 3.APR.2025 00:04:26

20MHz_High_QPSK_1@99




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 3.APR.2025 00:04:53

20MHz_High_QPSK_100@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 3.APR.2025 00:06:01

20MHz_High_16QAM_1@99



ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 3.APR.2025 00:11:06

20MHz_High_16QAM_100@0




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 3.APR.2025 00:08:19

Spurious Emissions at Antenna Terminal

FCC Part 22H


B5 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:55:40

1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:55:59

1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:56:17

3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:57:10

3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:57:29

3MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:57:45

5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:58:39

5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:58:55

5MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:59:11

10MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 21:00:01

10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 21:00:19

10MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 21:00:37

FCC Part 24E


B2 , Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:30:24

1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:33:09

1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:33:31

3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:34:28

3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:34:50

3MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:35:09

5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:36:10

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:36:29

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:36:48

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:37:50

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:38:10

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:38:30

15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:39:32

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:39:54

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:40:16

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:41:18

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:41:41

20MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:42:03


FCC Part 27

B4 , Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.55GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.55GHz)




3MHz_Low_QPSK_1@0(30MHz~18.55GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



3MHz_High_QPSK_1@0(30MHz~18.55GHz)




5MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:49:23

5MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:49:43

5MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:50:03

10MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:50:56

10MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:51:16

10MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:51:37

15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:52:25

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:52:46

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:53:07

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:54:03

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:54:25


20MHz_High_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 20:54:46


B7 , Normal
1RB was the worst case

5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502R38805E-RF Teeter:Loge Long
Date: 2.APR.2025 21:01:42

5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502R38805E-RF Teeter:Loge Long
Date: 2.APR.2025 21:02:04

5MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502R38805E-RF Teeter:Loge Long
Date: 2.APR.2025 21:02:28

10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502R38805E-RF Teeter:Loge Long
Date: 2.APR.2025 21:03:27

10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502R38805E-RF Teeter:Loge Long
Date: 2.APR.2025 21:03:51

10MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502R38805E-RF Teeter:Loge Long
Date: 2.APR.2025 21:04:14

15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 21:05:19

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 21:05:44

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 21:06:07

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 21:07:03

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 21:07:27

20MHz_High_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2502R38805E-RF Tester:Loge Long
Date: 2.APR.2025 21:07:51

**** END ****