



# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01


# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01


# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01


# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01



# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01



# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01

# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01


# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01

# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01



# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01


# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01



# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01




# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01





# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01



# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01



# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01


# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01



# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01



# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01


# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01



# INTERTEK TESTING SERVICE

Report No.: 15020700HKG-001

## Equipment Photographs

Model : 91763

(Internal)



FCC ID: PQN91763M012G4  
IC: 4438B-91763M01