

---

INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE


---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

# INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

## Equipment Photographs

Model : 91763

(Internal)



---

INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE


---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE



---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**



---

INTERTEK TESTING SERVICE

---

Report No.: 16030912HKG-001(FCC)  
16030912HKG-002 (IC)

**Equipment Photographs**

**Model : 91763**

**(Internal)**

