

Sensortronics Industries, Inc.
Strike Sensor
FCC ID#: PSW-SS2001

Photo Four
Battery Case Open with Battery removed – Programming Switches Accessable




Sensortronics Industries, Inc.
Strike Sensor
FCC ID#: PSW-SS2001

Photo Five
Battery Compartment Removed exposing the PCB – Open for Inspection




Sensortronics Industries, Inc.
Strike Sensor
FCC ID#: PSW-SS2001

Photo Six
PCB removed – Component Side




Sensortronics Industries, Inc.
Strike Sensor
FCC ID#: PSW-SS2001

Photo Seven
PCB removed – Trace Side



Sensortronics Industries, Inc.
Strike Sensor
FCC ID#: PSW-SS2001

Photo Eight
PCB close-up of Mercury Switch to engage RF Transmitter



**Sensortronics Industries, Inc.
Strike Sensor
FCC ID#: PSW-SS2001**

Photo Nine

**RC modification to provide 4 sec. Time Out on the transmitter
Updated schematic supports this modification.**

