

14085 Howard Rd  
Dayton, MD 21936

•  
•  
•  
•  
•  
**TRP Inc.**

February 23, 2004

Federal Communications Commission, Laboratory  
Oakland Mills RD  
Columbia, MD 21046

Gentlemen:

Submitted herewith is a request for a Class II permissive change for FCC ID:PT5TSU3000. This request is pursuant to changes in the layout of the RF output circuit requiring resubmission to the FCC. If you have any questions, please call Phillip Inglis at 410 531 3439 or contact via email at [jinglis@erols.com](mailto:jinglis@erols.com).

Sincerely,



Phillip Inglis  
Consultant

.....