

.....

14085 Howard Rd
Dayton, MD 21036

TRP/Cetecom bvba

August 31, 2001

FCC
7435 Oakland Mills Rd
Columbia, MD 21036


RE: TCB Application for Philips Components DSS device, FCC ID: PUB-WCM0001,
Confirmation Number: TC102200

Gentlemen:

This letter is to request the correction of the FCC ID listed on the FCC Form 731 for the reference application. Form 731 currently lists the identification as FCC ID:PUB-WCM0001. Please correct the Form 731 identification listing to read FCC ID:PUBWCM0001.

Sincerely,

Phillip Inglis
Consultant



.....