



3301 E. Deseret Drive, St. George, UT 84790
www.wilsonelectronics.com • info@wilsonelectronics.com
phone 1-800-204-4104 • fax 1-435-656-2432

May 3, 2016

Tuning and Adjustment of Wilson Model 460031 Signal Booster

There are no external tuning adjustments. The amplifier is factory set to not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Sincerely,

A handwritten signature in black ink, appearing to read 'P. L. Cook', is positioned above the printed name.

Patrick L. Cook
Chief Technology Officer