
Order Number: 11139405 Report Number: R11139405B-E2V3 Page 15 of 27

FCC ID: PY7-PM0943

Client Name: Sony Mobile Communications Inc. Issued: 2016-04-26

Figure 1 Test Setup for Conducted Emissions




Note: Laptop Ethernet was plugged into facility wall jack that was connected to facility switch, running ping session.

Order Number: 11139405 Report Number: R11139405B-E2V3 Page 21 of 27

FCC ID: PY7-PM0943

Client Name: Sony Mobile Communications Inc. Issued: 2016-04-26

Figure 4 Test setup for Radiated Emissions < 1GHz



Order Number: 11139405 Report Number: R11139405B-E2V3 Page 22 of 27

FCC ID: PY7-PM0943

Client Name: Sony Mobile Communications Inc. Issued: 2016-04-26

Figure 5 Test setup for Radiated Emissions > 1GHz

