



Sony Ericsson

Datum • Date

Beteckning • Reference

Confidential

1(1)

Vår handläggare, namn, tfn • Attending to this matter, name, telephone

Ert datum • Your date

Er beteckning • Your reference

Document number

Revision

BGLI08:832

A

Date

2008-09-25

Remarks

Prepared by

SEM/BGLIVM Kent Lorentzon + 46 10 80 19043

Contents responsible if other than preparer

Approved by

SEM/BGLIVMC Peter Lindeborg + 46 10 80 16180

Receiver: Federal Communication Commission and
Certification and Engineering Bureau
Industry Canada

Application PY7A3880002,

4170B-A3880002

Statement on WLAN hardware

Sony Ericsson mobile phone X1a (FCC ID PY7A3880002, IC: 4170B-A3880002) uses the exact same WLAN hardware and software as X1 (FCC ID PY7A3880001, IC: 4170B-A3880001).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 2-4883-57-06/08, dated 2008-09-12) issued for X1 also applies for X1a.

Best regards,

Peter Lindeborg

Technical Manager – EMF and Safety

Sony Ericsson Mobile Communications AB - Lund

Sony Ericsson Mobile Communications AB

Postadress • Mail
SE-221 88 Lund
Sweden

Besöksadress • Office address
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • Telephone
Nat 046-19 40 00
Int +46 46 19 40 00

Momsnr • V.A.T.No: SE556615665801
Organisationsnr • Reg No: 556615-6658
Telefax • Telefax
Nat 046-19 41 00
Int +46 46 19 41 00