



Vår handläggare, namn, tfn • Attending to this matter, name, telephone

Confidential

Ert datum • Your date

Er beteckning • Your reference 1(1)

Prepared by

SEM/BGLIVM Afrah Sadiq + 46 10 80 12250

Contents responsible if other than preparer

Document number

BGLI09:040

Date

2009-01-26

Remarks

Revision

A

Approved by

SEM/BGLIVMC Peter Lindeborg + 46 10 80 16180

Receiver: Federal Communication Commission and
Certification and Engineering Bureau
Industry Canada

Application: Type number AAD-3880010-BV, FCC ID: PY7A3880010,
IC: 4170B-A3880010.

Statement on Bluetooth hardware

Sony Ericsson mobile phone C510a (FCC ID: PY7A3880010, IC: 4170B-A3880010) uses the exact same Bluetooth hardware and software as C510 (FCC ID: PY7A3880009, IC: 4170B-A3880009).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 2-4883-65-04/08, dated 2009-01-08) issued for C510 also applies for C510a.

Best regards,

Peter Lindeborg

Technical Manager – EMF and Safety

Sony Ericsson Mobile Communications AB - Lund

Sony Ericsson Mobile Communications AB

Postadress • Mail
SE-221 88 Lund
Sweden

Besöksadress • Office address
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • Telephone
Nat 046-19 40 00
Int +46 46 19 40 00

Momsnr • V.A.T.No: SE556615665801
Organisationsnr • Reg No: 556615-6658
Telefax • Telefax
Nat 046-19 41 00
Int +46 46 19 41 00