



Sony Ericsson

Datum • Date

Beteckning • Reference

Vår handläggare, namn, tfn • Attending to this matter, name, telephone

Ert datum • Your date

Er beteckning • Your reference

Confidential

1(1)

Document number
CCDA09:384

Revision
A

Date
2009-07-02
Remarks

Prepared by

SEM/CCDALE Afrah Sadiq + 46 10 80 12250

Contents responsible if other than preparer

Approved by

SEM/CCMVA Mats Hansson + 46 10 802 33 57

Receiver: Federal Communication Commission and
Certification and Engineering Bureau
Industry Canada

Application: Type number: AAD-3880047-BV,

FCC ID: PY7A3880047

Canada IC: 4170B-A3880047

Statement on Bluetooth hardware

Sony Ericsson mobile phone U100a (FCC ID: PY7A3880047, IC: 4170B-A3880047) uses the exact same Bluetooth hardware and software as U100i (FCC ID: PY7A3880046, IC: 4170B-A3880046).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 1-1065-33-04/09, dated 2009-06-25) issued for U100i also applies for U100a.

Best regards

Mats Hansson

Head of Regulatory Compliance

Sony Ericsson Mobile Communications AB - Lund

Sony Ericsson Mobile Communications AB

Postadress • Mail
SE-221 88 Lund
Sweden

Besöksadress • Office address
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • Telephone
Nat 046-19 40 00
Int +46 46 19 40 00

Momsnr • V.A.T.No: SE556615665801
Organisationsnr • Reg No: 556615-6658
Telefax • Telefax
Nat 046-19 41 00
Int +46 46 19 41 00