



Friday, May 16, 2003

We (Net Inspect and RF Manufacturing Corp.) have changed R12 on the transmitter from a 47K resistor to a 18K resistor and will maintain that value in production.

Thank you,
Armen Kazanchian
RF Manufacturing
(Engineering and Manufacturing for Net Inspect)