

# INTERTEK TESTING SERVICE

Report No.: HK21040809

## Equipment Photographs

**(Internal)**





# INTERTEK TESTING SERVICE

Report No.: HK21040809

## Equipment Photographs

(Internal)





## INTERTEK TESTING SERVICE

---

Report No.: HK21040809

## Equipment Photographs

(Internal)




# INTERTEK TESTING SERVICE

Report No.: HK21040809

## Equipment Photographs

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK21040809

## Equipment Photographs

(Internal)





## INTERTEK TESTING SERVICE

---

Report No.: HK21040809

## Equipment Photographs

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK21040809

## Equipment Photographs

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK21040809

## Equipment Photographs

(Internal)




# INTERTEK TESTING SERVICE

Report No.: HK21040809

## Equipment Photographs

**(Internal)**



# INTERTEK TESTING SERVICE

Report No.: HK21040809

## Equipment Photographs

(Internal)



# INTERTEK TESTING SERVICE

Report No.: HK21040809

## Equipment Photographs

(Internal)

