

# **TIMCO** ENGINEERING INC.

849 NW State Road 45  
Newberry, Florida 32669  
<http://www.timcoengr.com>  
888.472.2424 F 352.472.2030 email: [tei@timcoengr.com](mailto:tei@timcoengr.com)

May 29, 2003

FCC

SUBJECT: SECURITAS AMERICA, INC. - FCC ID: Q3USBA-2000

## TYPOGRAPHICAL ERROR

To whom it may concern:

There is a typographical error on Page 5 of the Test Report. The bandwidth pulse measurement is stated to be 2.5 ms wide. The bandwidth plot on Page 6 shows the correct bandwidth to be 260 usec. The 260 usec bandwidth was used correctly to calculate the Duty Cycle Correction Factor.

Very truly yours,

Frank DeNuzzo