

Response to E04-000089-1

1. The FCC grantee code is correct. The company has changed their name from Inside Technologies to Inside Contactless.
2. A revised confidentiality letter has been uploaded.
3. The impedance of the EUT's transmitting antenna was adjusted to provide the desired emission level. The EUT position and cabling was maximized.
4. The -19dB correction was applied to the measurement of the Fundamental frequency which was measured at 10 meters. A revised test report has been uploaded with the correction on the fundamental table.
- 5-7. A revised users manual has been uploaded.