



November 5, 2009

Timco Engineering, Inc.  
Attn: Director of Certification

Subject: Tuning Procedures for the Model FS51C-45  
FCC ID: Q4VFS51C-45

This letter is to clarify the Tuning Procedure for our Model FS51C-45, UHF Channelized BDA is shipped from our factory ready for installation. There are no tuning elements which the customer is required to adjust. All and any tuning is sealed with final adjustments made at our factory prior to shipping.

*Linda Torocco*  
Linda Torocco  
Business Manager