

PALFINGER EUROPE GMBH | Moosmühlstraße 1 | 5203 Köstendorf | Austria

## Delay notification: RCP 915 RF

Köstendorf, February, 10<sup>th</sup> 2014

Dear Sir or Madame,

we are writing to you in order to confirm that the design of the RCP 915 RF has remained unchanged since the measurements were taken in March 2013.

However, the submission of the certification request was delayed due to administrative issues within Palfinger Group related on signature procedure and Project Management responsibilities.

Best Regards,



Bernhard Wieder

(Head of Mechatronics Development and Patent Management)